

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



1. Lease sign at well location at time of inspection.



2. View of wellhead.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



3. View of vegetation growing inside well fencing.



4. Broken post allowing fencing to separate and give cattle access into well fencing.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056




5. View of Pump Jack.



6. Well location overview.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



7. Lease sign at Production Facility at time of inspection.



8. View of Separator/Meter Shed. Note vegetation.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



9. View of Vertical Separator inside shed.



10. Digital gas meter inside shed.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



11. Calibration/Test Log inside meter shed.



12. Trash inside Meter Shed.

Inspection Photos
Location Name: Price 13-25
API Number: 115-06056



13. Additional well location overview.



14. Remote metering location overview.