

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/21SWNW

Location ID: 335257

Date: 6/18/2024



Wellheads – Photo #01809



Separators/Chem Tank – Photo #01804

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/21SWNW

Location ID: 335257

Date: 6/18/2024



Tank Battery – Photo #01806



Gas Meter – Photo #01805