

**Inspection Photos**  
**Location Name: Antelope 21-17 PAD**  
**Location ID: 404901**



**Photo 1 – Pumping Unit**



**Photo 2 – Gas Engine**

**Inspection Photos**  
**Location Name: Antelope 21-17 PAD**  
**Location ID: 404901**



**Photo 3 – Wellheads – Panels in disrepair**



**Photo 4 – Wellhead**



**Inspection Photos**  
**Location Name: Antelope 21-17 PAD**  
**Location ID: 404901**



**Photo 5 – Separators and ECD – Tumbleweeds**



**Photo 6 – Tank Battery**

Inspection Photos  
Location Name: Antelope 21-17 PAD  
Location ID: 404901



Energy and Carbon Management Commission  
40.40545, -104.34938, 4648.6ft  
06/24/2024 13:23:34



Energy and Carbon Management Commission  
40.40546, -104.3494, 4651.8ft  
06/24/2024 13:23:41

Photo 7 – Tank Battery Sign

Photo 8 – Tank Battery Signs