

**Inspection Photos**  
**Location Name: Antelope 43-17 PAD**  
**Location ID: 424559**



**Photo 1 – Sign at Entrance**



**Photo 2 – Separators and ECD – Tumbleweeds**

**Inspection Photos**  
**Location Name: Antelope 43-17 PAD**  
**Location ID: 424559**



**Photo 3 – Tank Battery**



**Photo 4 – Tank Battery Signs**




**Inspection Photos**  
**Location Name: Antelope 43-17 PAD**  
**Location ID: 424559**



Energy and Carbon Management Commission  
40.39855, -104.34064, 4635.8ft  
06/24/2024 13:33:35

**Photo 5 – Tank Battery Signs**




Energy and Carbon Management Commission  
40.3984, -104.34068, 4642.8ft  
06/24/2024 13:35:15

**Photo 6 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Antelope 43-17 PAD**  
**Location ID: 424559**



**Photo 7 – Unmarked 1" Risers**



**Photo 8 – Unmarked 1" Riser**