

Inspection Photos  
Location Name: Antelope I-17 PAD  
Location ID: 420880




Photo 1 – Sign at Entrance

Photo 2 – Wellheads



**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 3 – 1" Riser not marked**



**Photo 4 – 1" Riser not marked**



**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 5 – 1" Riser not marked**



**Photo 6 – 1" Risers not marked**



**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 7 – Wellheads**



**Photo 8 – Tank Battery**

Inspection Photos  
Location Name: Antelope I-17 PAD  
Location ID: 420880



Photo 9 – Tank Battery Signs

Photo 10 – Tank Battery Signs



Inspection Photos  
Location Name: Antelope I-17 PAD  
Location ID: 420880



Photo 11 – Tank Battery Signs



Photo 12 – ECD and Separator – Tumbleweeds

**Inspection Photos**  
**Location Name: Antelope I-17 PAD**  
**Location ID: 420880**



**Photo 13 – Separator – Tumbleweeds**