

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 1284 From entrance to location



Photo # 1285 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 1286 Location



Photo # 1287 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 1288 Location



Photo # 1289 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 1290 Location



Photo # 1291 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 1292 Wellhead sign weathered & cracking/starting to become illegible



Photo # 1293 Wellhead sign weathered & cracking/starting to become illegible



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



**Photo # 1294 Wellhead sign weathered & cracking/starting to become illegible**