

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403838635

Date Received:
06/27/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000869

Inspection Date: 06/18/2024

FIR Submit Date: 06/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326188

Location Name: BROWN 32-6-3-N32N6W Number: 3NWSW County: _____

Qtrqtr: NWS Sec: 3 Twp: 32N Range: 6W Meridian: N

Latitude: 37.044521 Longitude: -107.492236

FACILITY - API Number: 05-067- -00 Facility ID: 326188

Facility Name: BROWN 32-6-3-N32N6W Number: 3NWSW

Qtrqtr: NWS Sec: 3 Twp: 32N Range: 6W Meridian: N

Latitude: 37.044521 Longitude: -107.492236

CORRECTIVE ACTIONS:

1 CA# 196102

Corrective Action: Comply with rule 605. Install or repair sign.

Date: 07/24/2024

Response: CA COMPLETED

Date of Completion: 06/27/2024

Operator
Comment: Sign repaired

ECMC Decision: _____

Date:

Date of Completion: 06/27/2024

Debris removed

ECMC Decision: _____

--

Partial CA completed. See attached photos.

Signed: _____

Date: 6/27/2024 12:26:28 PM

403838653	Partial CA completed for Brown 32-6-3-1
-----------	---

Page 2 of 2