

Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325656

Inspection Document #: 714000881

La Plata County, CO

Township: SWSE 29 33N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute 29-01 2
Location ID: 325656

6/18/24
+37.071574,-107.545708
63° NE



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Southern Ute 29-01 2
Location ID: 325656



6/18/24
+37.070328,-107.520963
102° E

Photo 2. View of the southern interim reclamation area facing east.