

Final Reclamation and Stormwater Inspection

Date: 6/25/24

Operator: Extraction Oil & Gas Inc - 10459

Location ID: 319519

Inspection Document #: 713900701

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hippen #1-32
Location ID: 319519



Photo 1. The photo was taken at the well location facing North. The photo illustrates the well location has reached final reclamation compliance in the horse pasture.

Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hippen #1-32
Location ID: 319519



Photo 3. The photo was taken at the well location facing South. Refer to the comment for photo 1.

Photo 4. The photo was taken at the well location facing West. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hippen #1-32
Location ID: 319519



Photo 5. The reference photo was taken of the pasture to the East facing East. The photo illustrates dominance of Smooth brome and Crested wheatgrass.

Inspection Photos
Location Name: Hippen #1-32
Location ID: 319519



Photo 6. The photo was taken at the tank battery location facing West. The photo illustrates dominance of Smooth brome and Crested wheatgrass.

Photo 7. The photo was taken at the tank battery location facing Northeast. Refer to the comments for photo 6.

Note - A sprinkler system has been set up along the tank battery footprint.

Inspection Photos
Location Name: Hippen #1-32
Location ID: 319519



Photo 8. The tank battery reference photo was taken to the East facing East. The photo illustrates dominance of Smooth brome and Crested wheatgrass.