

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SENE

Location ID: 335450

Date: 6/26/2024



North Entrance/Exit of Location – Photo #01843



West End of Location – Photo #01844

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SENE

Location ID: 335450

Date: 6/26/2024



Wellheads – Photo #01845



Separators – Photo #01848

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SENE

Location ID: 335450

Date: 6/26/2024



Tank Battery – Photo #01846

