

Inspection Photos
Location Name: David Howard B 3
Location ID: 318352



Pic 1 pump jack / wellhead. Weeds may need to be addressed soon



Pic 2 wellhead sign