

**Inspection Photos**  
**Location Name: Linnebur 1**  
**Location ID: 319737**



**Pic 1 wellhead / pump jack**



**Pic 2 contaminated soil by wellhead**



**Inspection Photos**  
**Location Name: Linnebur 1**  
**Location ID: 319737**



**Pic 3 Wellhead sign inadequate**



**Pic 4 risers are not LOTO**



**Inspection Photos**  
**Location Name: Linnebur 1**  
**Location ID: 319737**



**Pic 5 Weeds unmanaged**



**Pic 6 deadmen are not marked properly**

**Inspection Photos**  
**Location Name: Linnebur 1**  
**Location ID: 319737**

Jun 26, 2024 at 12:57:05 PM  
39.958723,-103.938803  
ECMC



**Pic 7 deadmen not marked properly**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources