

Inspection Photos

Location: Laramie Energy LLC Hawxhurst Ranch/24-09 Pad

Location ID: 419498

Date: 6/25/2024



Entrance to location - Photo #02908



Location - Photo #02924

Inspection Photos

Location: Laramie Energy LLC Hawxhurst Ranch/24-09 Pad

Location ID: 419498

Date: 6/25/2024



Well heads - Photo #02910



Separators - Photo #02920

Inspection Photos

Location: Laramie Energy LLC Hawxhurst Ranch/24-09 Pad

Location ID: 419498

Date: 6/25/2024



Separators - Photo #02921



Tank battery - Photo #02922

Inspection Photos

Location: Laramie Energy LLC Hawxhurst Ranch/24-09 Pad

Location ID: 419498

Date: 6/25/2024



Northwest corner of location - Photo #02930



Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/not sufficient to contain possible spill - Photo #02914

Inspection Photos

Location: Laramie Energy LLC Hawxhurst Ranch/24-09 Pad

Location ID: 419498

Date: 6/25/2024



Chemical containment open to wildlife - Photo #02917



Chemical containment open to wildlife - Photo #02919