

**Inspection Photos**  
**Location Name: Antelope 21-19 PAD**  
**Location ID: 418233**



**Photo 1 – L-19 Wellhead**



**Photo 2 – L-19 Wellhead Sign – Faded no longer visible**



**Inspection Photos**  
**Location Name: Antelope 21-19 PAD**  
**Location ID: 418233**



**Photo 3 – Wellheads**



**Photo 4 – Wellhead – Unused Automation Equipment**



**Inspection Photos**  
**Location Name: Antelope 21-19 PAD**  
**Location ID: 418233**



**Photo 5 – Unused Automation Equipment**



**Photo 6 – Wellhead Sign – Faded no longer visible**



**Inspection Photos**  
**Location Name: Antelope 21-19 PAD**  
**Location ID: 418233**



**Photo 7 – Unused Automation Equipment**



**Photo 8 – Antelope F-19 Nightcap – Plugged waiting on Cut and Cap**