

# Orphan Well Inspection

April 18, 2024

Operator: Larry Javernick #44394

Location ID: 426290

Inspection Document #: 709401043

Fremont County, CO

NESW Section 35 T18S R70W

Reed Wold

OWP Reclamation Specialist, CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Javernick 1 DM  
Location ID: 426290



**Photo 1.** Photo of well pad, pipe riser is the only equipment on site. Dark bare, possibly stained soil on pad.

**Photo 2.** Photo of well pad facing north, Dark bare, possibly stained soil on pad.

Inspection Photos  
Location Name: Javernick 1 DM  
Location ID: 426290



**Photo 3.** Photo of well pad facing West, Dark bare, possibly stained soil on pad.



**Photo 4.** Photo of drainage crossing well pad, bare soil highly erodible.

**Inspection Photos**  
**Location Name: Javernick 1 DM**  
**Location ID: 426290**



**Photo 5.** Photo of what appears to be volcanic rock on well pad, no vegetation on pad.



**Photo 6.** Photo standing on well pad facing east of surrounding vegetation.

**Inspection Photos**  
**Location Name: Javernick 1 DM**  
**Location ID: 426290**



**Photo 7.** Photo of well pad facing northwest, Dark bare, possibly stained soil on pad.



**Photo 8.** Photo of well pad facing Northwest.