

Final Reclamation and Stormwater Inspection

Date: 6/25/24

Operator: Extraction Oil & Gas Inc - 10459

Location ID: 327754

Inspection Document #: 713900719

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hippen #2-32
Location ID: 327754



Photo 1. The photo was taken at the well location facing North. The photo illustrates the former well location is dominated by Knapweed, Field bindweed, Sweetclover and cover of Scotch thistle, Quackgrass and Smooth brome.

Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hippen #2-32
Location ID: 327754



ECMC
181° S
6/25/24, 10:02 AM

Photo 3. The photo was taken at the well location facing South. Refer to the comment for photo 1.



ECMC
267° W
6/25/24, 10:02 AM

Photo 4. The photo was taken at the well location facing West. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hippen #2-32
Location ID: 327754



ECMC
133° SE
6/25/24, 10:03 AM

Photo 5. The photo was taken at the well location facing Southeast. The photo illustrates large blocks left at the well location that are accumulating noxious weeds.



ECMC
263° W
6/25/24, 10:04 AM

Photo 6. The photo was taken at the tank battery location facing West.



Inspection Photos
Location Name: Hippen #2-32
Location ID: 327754



Photo 7. The reference photo was taken near the well location facing East. The photo illustrates reference areas are dominated by Smooth brome.