

Final Reclamation and Stormwater Inspection

Date: 6/25/24

Operator: Extraction Oil & Gas Inc - 10459

Location ID: 463225

Inspection Document #: 713900721

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Hippen 32-2,13; Pezoldt UU

32-4J

Location ID: 463225



Photo 1. The photo was taken at the tank battery location facing East. The photo illustrates bare soil, Kochia, field bindweed and Saltgrass dominate the location.



Photo 2. The photo was taken at the tank battery location facing West. Refer to the comment for photo 1.

Inspection Photos

Location Name: Hippen 32-2,13; Pezoldt UU

32-4J

Location ID: 463225



Photo 3. The reference photo was taken near the tank battery location facing West. The photo illustrates reference areas along the gravel road are dominated by Smooth Brome.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Number: 713900721