

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: BUZZARD CREEK # 22-3

Location ID: 334554 API #: 05-077-08765

Inspection Date: 6/26/2024 Inspection Doc#: 693807457



Injection wellhead inside housing



Pump Housing.



Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: BUZZARD CREEK # 22-3

Location ID: 334554 API #: 05-077-08765

Inspection Date: 6/26/2024 Inspection Doc#: 693807457



Tank battery



Separators

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: BUZZARD CREEK # 22-3

Location ID: 334554 API #: 05-077-08765

Inspection Date: 6/26/2024 Inspection Doc#: 693807457



Flowline



Pig Station