

## Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: VEGA UNIT # 34-13D

Location ID: 334489 API #: 05-077-09042

Inspection Date: 6/26/2024 Inspection Doc#: 693807459



Injection wellhead inside housing



Pump Housing.

## Inspection Photos

**Operator: LARAMIE ENERGY LLC - 10433**

**Location Name: VEGA UNIT # 34-13D**

**Location ID: 334489    API #: 05-077-09042**

**Inspection Date: 6/26/2024    Inspection Doc#: 693807459**



**Tank battery**



**Separators**



## Inspection Photos

**Operator: LARAMIE ENERGY LLC - 10433**

**Location Name: VEGA UNIT # 34-13D**

**Location ID: 334489    API #: 05-077-09042**

**Inspection Date: 6/26/2024    Inspection Doc#: 693807459**



**Tank battery**



**Meter housing  
Secondary containment od chemicals**

