

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 1926 From entrance to location



Photo # 1927 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 1928 Location



Photo # 1929 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 1930 Location



Photo # 1931 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 1932 Chemical tank label starting to peel & some required info is not visible



Photo # 1933 Tank label weathered & starting to become illegible