

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope 21-17PAD

Loc ID: 404901

Inspection: 696306471



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Panels are in disrepair; see photos, Comply with Rule 606

CA Resolution: Operator reported that panels have been appropriately re-installed. It was also reported that debris/tumbleweeds have been cleared, as well. Location complies with Rule 606.