

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope K-15 Pad

Loc ID: 435681

Inspection: 696306461



Exhibit A



Exhibit B

CA: MT-56 Container STILL Missing Label; see photos. Same Corrective Action Date remains, Install sign to comply with Rule 605.h.

CA Resolution: Operator has reported that labels have been appropriately installed on identified containers to comply with Rule 605.h.