

Inspection Photos

Location: WRIGHT,SMALLWOOD,CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 6/24/2024



Entrance to location - Photo #02885



Location - Photo #02895

Inspection Photos

Location: WRIGHT,SMALLWOOD,CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 6/24/2024



Well heads - Photo #02886



Separators - Photo #02888

Inspection Photos

Location: WRIGHT,SMALLWOOD,CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 6/24/2024



Open ended piping/wildlife hazard - Photo #02890



Tank battery - Photo #02893

Inspection Photos

Location: WRIGHT,SMALLWOOD,CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 6/24/2024



Northwest corner of location - Photo #02898



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources