


Inspection Photos

Location Name: South Holyoke SWD 1B-25-7-45

API Number: 095-06169



1. Lease sign at wellhead.



2. View of wellhead.

Inspection Photos
Location Name: South Holyoke SWD 1B-25-7-45
API Number: 095-06169



3. Tubing pressure at time of inspection.



4. Casing pressure (vacuum) at time of inspection.

Inspection Photos
Location Name: South Holyoke SWD 1B-25-7-45
API Number: 095-06169



5. Well site overview. Note vegetation across location.



6. Well site overview. Note vegetation.

Inspection Photos

Location Name: South Holyoke SWD 1B-25-7-45

API Number: 095-06169



7. Steel injection pump and equipment building at tank battery. Note vegetation.



8. Filter pots inside injection building. Injection pump has been removed.

Inspection Photos

Location Name: South Holyoke SWD 1B-25-7-45

API Number: 095-06169



9. Stained soil inside injection pump building.



10 View of Tank Battery. Note vegetation and rusting tank.

Inspection Photos
Location Name: South Holyoke SWD 1B-25-7-45
API Number: 095-06169



11. View of peeling, fading, and unreadable labels on tank.



12. View of vegetation growing on and inside tank berms.

Inspection Photos
Location Name: South Holyoke SWD 1B-25-7-45
API Number: 095-06169



13. Location overview. Note vegetation.



14. Location overview. Note vegetation.

Inspection Photos
Location Name: South Holyoke SWD 1B-25-7-45
API Number: 095-06169



15. Location overview. Note vegetation.



16. Location overview. Note vegetation.