

**Operator: BCEI**  
**Location Name: Antelope I-29**  
**Loc ID: 422173**  
**Inspection: 696306431**



Exhibit A



Exhibit B



**Exhibit C**

**CA:** Heat Exhaust Stacks have been removed. Separators open to the Atmosphere need to be closed. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

**CA Resolution:** Operator has reported that the burner stacks have been appropriately covered to comply with Rule 902.b.