

Inspection Photos

June 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333704

Inspection Document #: 714000895

La Plata County, CO

Township: NWSW 24 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Federal Land Bank G2, G4
Location ID: 333704

6/25/24
+37.086897,-107.783125
20° N



6/25/24
+37.086937,-107.783378
48° NE



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos

Location Name: Federal Land Bank G2, G4

Location ID: 333704



Photo 2. Patches of Russian knapweed observed flowering in the western interim reclamation area.

Inspection Photos
Location Name: Federal Land Bank G2, G4
Location ID: 333704



Photo 3. Gully erosion observed forming in the northern interim reclamation area.