

Inspection Photos

June 25th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311912

Inspection Document #: 714000897

La Plata County, CO

Township: NSW E 13 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis Gas Unit
Location ID: 311912




Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Davis Gas Unit
Location ID: 311912



6/25/24
+37.100523,-107.773493
155° SE

Photo 2. View of the eastern interim reclamation area facing south east.

Inspection Photos
Location Name: Davis Gas Unit
Location ID: 311912



6/25/24
+37.100451,-107.774393
264° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of sage brush and smooth brome.

API #: 067-07882, 09603