

Inspection Photos
Location Name: Walsh 3
Location ID: 336468



Photo 1 Wellsite ROW overgrown with vegetation.



Photo 2 WH.

Inspection Photos
Location Name: Walsh 3
Location ID: 336468



Photo 3 WH sign.

Photo 4 Damaged WH fence.

Inspection Photos
Location Name: Walsh 3
Location ID: 336468



Photo 5 Large hay bales set as sound damper are degrading falling down and need to be addressed.

Photo 6 Wellsite ROW overgrown with vegetation.

Inspection Photos
Location Name: Walsh 3
Location ID: 336468



Photo 7 Large hay bales set as sound damper are degrading, falling down and need to be addressed.

Photo 8 Large hay bales set as sound damper are degrading, falling down and need to be addressed.

Inspection Photos
Location Name: Walsh 3
Location ID: 336468



Photo 9 Large hay bales set as sound damper are degrading, falling down and need to be addressed.

Photo 10 Prime Mover.