

# Inspection Photos

06/25/2024

**Operator:** ROBERT L BAYLESS PRODUCER LLC  
#6720

**Location ID:** 316762

**Inspection Doc:** 696205936

Routt County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 1:** Photo taken with use of a sUAS. Photo taken from the southwest of the Location, facing northeast; photo provides an overview of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 2:** Photos 2-3 taken from the Location entrance on the east end of the site. Photos provide an overview from southwest, west north to northeast. Photos show Location has not been reclaimed in accordance with 1004 rules. Locations is predominantly Undesirable Plant Species or bare/exposed soils. Unable to find evidence that topsoil has been replaced, or exists on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 4:** Photo example showing access road has not been recontoured/regraded and reclaimed in accordance with 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 5:** Continued from photo 4. Aerial image showing access road has not been recontoured/regraded and reclaimed in accordance with 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 6:** Photos 6-7 examples showing noxious weed establishment on the Location. Weeds observed include Houndstongue, Canada thistle, Bulbous Bluegrass, Bull thistle and Field Bindweed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 7:** See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 8:** Photos taken from the western areas of the Location. Photos examples showing stormwater and erosion control monitoring and management also does appear to be occurring; BMPs to manage runoff in a manner that minimizes erosion, degradation and sediment transport was not observed. Gully erosion observed; hat in photo right for reference.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 9:** Photo showing areas on the west end of the Location where stormwater issues were observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 10:** Aerial image showing areas on the west end of the Location where stormwater issues were observed. Erosion degradation observed throughout the slopes of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC #6720

Location ID: 316762



**Photo 11:** Photo taken from the access road. Photo examples showing erosion degradation issues observed on the road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources