

# Inspection Photos

06/25/2024

**Operator:** ROBERT L BAYLESS PRODUCER LLC -  
6720

**Location ID:** 316765

**Inspection Doc:** 696205940

Routt County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 1:** Photos taken from the Location entrance on the southwest end of the Location. Photos provide an overview of the Location from north and east



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 2:** Stained soils observed on the west end of the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 3:** Photo shows former battery facility location on the east end of the site. Remediation for facility closure is in process.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 4:** Photo taken from the northwest end of the Location. Photo shows remaining pipe riser equipment. Equipment requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 5:** Continued from photo 4. Pipe has not been capped. BMPs to prevent access by wildlife, including bats/birds required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 6:** Photo shows anchor equipment remaining on the east end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ROBERT L BAYLESS PRODUCER LLC - 6720

Location ID: 316765



**Photo 5:** Photos examples showing the access road has not been recontoured/regraded and reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources