

Inspection Photos

06/25/2024

Operator: BEEMAN OIL & GAS INC - 7125

Location ID: 316756

Inspection Doc: 696205942

Routt County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from northwest, north, east to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 2: See Comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 3: Photos examples showing weeds on the working pad surface and interim areas of the Location continue to spread and establish. Weeds observed include Bull thistle (photo left), Canada thistle (Photo right), Houndstongue (Photo #4), etc...



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 5: Unused pipe observed sticking out of the pad surface on the south end of the Location.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 6: Photo example showing pipes used to mark anchors on Location has not been properly closed to prevent access by wildlife, including birds and bats.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 7: Photo taken from the well. Photo shows unused tote container (red arrow) remains stored on the Location. Photo also shows vegetation remains established around production equipment (yellow arrows).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 8: Stained soils have not been cleaned/removed at the well

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 9: Stained soils have not been cleaned/removed at the well

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 10: Stained soils have not been cleaned/removed at the well. Trash/debris/oily rags evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 11: Stained soils have not been cleaned/removed at the well. Trash/debris/unused equipment remaining.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



June 25, 2024

Photo 12: Photo shows 90 bbl produced water tank. Secondary containment remains insufficient to contain a spill or release. Battery at the facility and tank not per Rules 605.e and 605.h



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 13: Photos taken from separator equipment. Photo shows covers have not been replaced at equipment. BMPs to prevent wildlife equipment remain missing or insufficient.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 14: Leak at separator and stained soils have not been stopped or cleaned.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 15: Stained soils have not been cleaned/removed at the separator. Trash/debris/unused equipment remaining.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 16: BMPs pursuant to Rule 1002.c remain missing at the soil stockpile.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 17: Photos show vegetation remains established on and within the secondary containment base and berm; vegetative establishment compromises the integrity of the containment BMP, and requires removal.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 18: Stained soils at loadlines/tanks

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 316756



Photo 19: Stained soils on the north end of the working pad surface.