

Inspection Photos

API: 071-08708

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 6/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. There has been recent weed control performed at wellsites in the area. Blue dye was observed on weeds at red arrow.



Inspection Photos



Photo 2. Facing northwest toward the wellsite.



Inspection Photos



Photo 3. There is a E&P waste pile of pit material stored by the pit that needs to be removed..



Inspection Photos



Photo 4. Facing toward the pit which is now unlined.



Inspection Photos



Photo 5. The sound wall is not in use and should be removed..

