

Stormwater Inspection

Date: 7/2/24

Operator: Noble Energy Inc - 100322

Location ID: 329434

Inspection Document #: 713900744

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Smith-64N64W 9SWNW

Location ID: 329434



Photo 1. The photo is an Operator photo from FIRR #403835323 demonstrating soil staining clean-up has been completed at the tank battery location.

Inspection Photos

Location Name: Smith-64N64W 9SWNW

Location ID: 329434



Photo 2. The photo is an Operator photo from FIRR #403838786 demonstrating the Operator has attempted to slow erosion on the tank battery location with a small berm.

Note - Erosion has yet to be repaired off location in the alfalfa field.

Inspection Photos
Location Name: Smith-64N64W 9SWNW
Location ID: 329434



Photo 3. The photo is an Operator provided photo demonstrating the Operator has attempted to slow erosion on the tank battery location with a small berm. However the pivot seen in the background is causing ponding on the tank battery due to installed BMP's.