

Inspection Photos

API: 071-09423

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southwest toward the wellsite.



Inspection Photos



Photo 2. Facing toward the produced water pit. The liner is torn and degraded. There is grey drilling mud in the upper pit that needs to be cleaned out and removed. A form 27 will need to be submitted due to compromised pit.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09423 | Date: 7/2/2024

Inspection Photos



Photo 3. Facing northeast at the location. The well sign is posted at the north side of the location..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09423 | Date: 7/2/2024