

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Location Entrance – Photo #01933



South End of Location – Photo #01940

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Jun 27, 2024 at 11:02:04
Parachute CO 81635
United States

Wellheads – Photo #01942



Jun 27, 2024 at 10:57:50
Parachute CO 81635
United States

Separators – Photo #01934

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Tank Battery – Photo #01936



Tank Battery – Photo #01949

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Tank Battery – Photo #01955



Heater Treater – Photo #01958

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Covered Pit – Photo #01948



Pit – Photo #01961

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Housekeeping/Unused Supplies/Equipment – Photo #01957



Housekeeping/Unused Supplies/Equipment – Photo #01966

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Housekeeping/Unused Supplies/Equipment – Photo #01968



Open-Ended Line at Pit – Photo #01960

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Open-Ended Line at Pit – Photo #01962



Open-Ended Line at Pit – Photo #01963

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Open-Ended Line at Pit – Photo #01964



Open-Ended Line at Pit – Photo #01967

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE

Location ID: 335601

Date: 6/27/2024



Open-Ended Load Line – Photo #01937



Open-Ended Load Line – Photo #01938