

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/8NENW

Location ID: 335627

Date: 6/27/2024



Wellhead – Photo #01983



Separator/Methanol Tank – Photo #01978



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/8NENW

Location ID: 335627

Date: 6/27/2024



Tank Battery – Photo #01972



Pit – Photo #01980

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/8NENW

Location ID: 335627

Date: 6/27/2024



Stored Equipment on Location – Photo #01979



Open-Ended Line – Photo #01974

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/8NENW

Location ID: 335627

Date: 6/27/2024



Open-Ended Load Line – Photo #01975



Open Wellhead Cellar – Photo #01986

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/8NENW

Location ID: 335627

Date: 6/27/2024



Sediment Run-Off from Location – Photo #01981