

# Inspection Photos

API: 071-09296

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing east along the access road..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-09296 | Date: 7/2/2024

Inspection Photos



**Photo 2.** Facing northeast toward the wellsite.



## Inspection Photos



**Photo 3.** There is stained soil by the engine sound wall that must be cleaned up.



## Inspection Photos



**Photo 4.** There is stained soils by the wellhead that needs to be cleaned up.



## Inspection Photos



**Photo 5.** Facing southeast at the location.

