

Inspection Photos

API: 071-07508

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07508 | Date: 7/2/2024

Inspection Photos



Photo 2. Facing northeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07508 | Date: 7/2/2024

Inspection Photos



Photo 3. There is oily fluids in the engine skid that needs to be cleaned up.

