

Inspection Photos

Location Name: Lenz Farms SWD 3B-32-5-43

API Number: 125-11079



1. Lease sign at Location entrance.



2. View of wellhead. Note missing Bull plugs.

Inspection Photos
Location Name: Lenz Farms SWD 3B-32-5-43
API Number: 125-11079



3. Tubing pressure at time of inspection.



4. Casing pressure at time of inspection.

Inspection Photos

Location Name: Lenz Farms SWD 3B-32-5-43

API Number: 125-11079



5. Lease sign on metal shed at Tank Battery.



6. View of Tank Battery. Note vegetation inside berms and berms flatness due to wear.

Inspection Photos

Location Name: Lenz Farms SWD 3B-32-5-43

API Number: 125-11079



7. Metal building leaning and off footings.



8. Inside metal shed. Trash, debris, unused equipment, open ended flowlines, and broken off panel supports.

Inspection Photos
Location Name: Lenz Farms SWD 3B-32-5-43
API Number: 125-11079



9. View of Steel AST's. Note rust at valve area on right tank.



10. View of vegetation inside bermed area.

Inspection Photos
Location Name: Lenz Farms SWD 3B-32-5-43
API Number: 125-11079



11. View of one of the Pig Stations. Stock Panels are down lying on the ground. Cattle tracks around station.



12. Chemical Tank inside secondary containment. Located at Pig Station. Tank has no labels.

Inspection Photos

Location Name: Lenz Farms SWD 3B-32-5-43

API Number: 125-11079



13. View looking from wellhead towards tank battery. Note vegetation.



14. Location overview. Note vegetation.