

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403802229

Date Received:

05/24/2024

Spill report taken by:

Robinson, Taylor

Spill/Release Point ID:

487225

### SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

#### OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-0055</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>( )</u>
Contact Person: <u>Jaron Bartoszek</u>		Email: <u>DJRemediation_Forms@oxy.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

#### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403802229

Initial Report Date: 05/23/2024 Date of Discovery: 05/23/2024 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR SESW SEC 13 TWP 3N RNG 67W MERIDIAN 6

Latitude: 40.220011 Longitude: -104.842809

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

#### Reference Location:

Facility Type: TANK BATTERY

Facility/Location ID No 446131

Spill/Release Point Name: Gunzner 12&13-13A FAC Hist. Release

Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: CROP LAND \_\_\_\_\_

Other(Specify): \_\_\_\_\_

Weather Condition: FAIR, ~55 Degrees F \_\_\_\_\_

Surface Owner: FEE \_\_\_\_\_

Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On May 23, 2024, historically impacted soil was discovered below the former produced water vessel (PWV) location following decommissioning activities at the Gunzner 12&13-13A Production Facility site. Excavation and assessment activities are ongoing. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
5/24/2024	CO Parks & Wildlife	L. Hamous-Miller	-email	
5/24/2024	Landowner	Private	-email	
5/24/2024	Weld County	J. Maxey	-email	
5/24/2024	Weld County	R. Rudisill	-email	

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
 Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
 Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location  Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>05/23/2024</u>		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: _____		Length of Impact (feet): <u>10</u>	
		Width of Impact (feet): <u>10</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
<p>Following tank battery decommissioning activities at the Gunzner 12&amp;13-13A Production Facility location on May 22, 2024, seven (7) confirmation soil samples were collected from the locations of the former facility infrastructure. The soil samples were submitted for laboratory analysis of the full ECMC Table 915-1 analytical suite, using standard methods appropriate for detecting the target analytes. Preliminary analytical results indicate that the TMB and/or TPH concentrations in soil samples PW-N01@3" and PW-W01@3" exceeded the ECMC Table 915-1 Protection of Groundwater Soil Screening Level Concentrations. Preliminary analytical results indicate that constituent concentrations in the remaining soil samples collected during facility decommissioning activities were in compliance with the applicable ECMC Table 915-1 standards. Additional analytical results for the soil samples collected on May 22, 2024 are pending laboratory analysis and final reporting. Excavation and site assessment activities are ongoing and will be summarized in a forthcoming quarterly Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 34360 (approved Form 27-Initial Document No. 403683931). A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. Soil sample location and field screening data are provided in Table 1. Field notes and a photographic log are provided as Attachment A. The State Notification email is provided as Attachment B.</p>			
Soil/Geology Description:			
SC - Clayey Sand			

Depth to Groundwater (feet BGS) 20 Number Water Wells within 1/2 mile radius: 12  
 If less than 1 mile, distance in feet to nearest Water Well 390 None  Surface Water 1040 None   
 Wetlands 700 None  Springs          None   
 Livestock 2600 None  Occupied Building 1060 None

Additional Spill Details Not Provided Above:

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 05/23/2024

Root Cause of Spill/Release Unknown (Historical)

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Produced water vessel

Describe Incident & Root Cause (include specific equipment and point of failure)

Historically impacted soil was discovered below the former PWV location following production facility decommissioning activities.

Describe measures taken to prevent the problem(s) from reoccurring:

The affected infrastructure has been removed and will not be replaced.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

### REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).
    - Form 27 Remediation Project No: 34360
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

**OPERATOR COMMENTS:**

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jaron Bartoszek

Title: Environmental Advisor Date: 05/24/2024 Email: DJRemediation\_Forms@oxy.com

**COA Type**

**Description**

	Quarterly reporting (90 days) is required under Remediation Project #34360. Operator shall include the Spill ID associated with this form on the subsequent Supplemental Form 27 and select Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912 in addition to the previous Rule selection.
1 COA	

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

403802229	SPILL/RELEASE REPORT(I/S)
403802427	PHOTO DOCUMENTATION
403802429	TOPOGRAPHIC MAP
403802450	OTHER
403802822	CORRESPONDENCE
403845285	FORM 19 SUBMITTED

Total Attach: 6 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)