

# Inspection Photos

API: 071-07685

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing east along the preexisting access road.



## Inspection Photos



**Photo 2.** The culverts along the road are maintained.



## Inspection Photos



**Photo 3.** Facing east along the road. There has been weed control recently performed.



## Inspection Photos



**Photo 4.** Facing southeast toward the recontoured and reclaimed location.



## Inspection Photos



**Photo 5.** The location is stabilized with long term BMP's.



## Inspection Photos



**Photo 6.** Facing southwest at the location. The perennial vegetation has uniformly established.



## Inspection Photos



**Photo 7.** Facing southeast at beginning of transect at the location.



**Photo 8.** Facing southeast at end of transect at the location.



## Inspection Photos



**Photo 9.** Facing west at beginning of transect at reference area.



**Photo 10.** Facing east at end of transect at reference area



