



Inspection Photos

Location Name: Iles

Location ID: 483727

Remediation Project #: 28246

Inspection Date: 7/2/2024

Photo#1 north of county road. Some algal observable in the water



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo #2 south of the county road, "culvert" area. It did not appear that any recent work has been completed.

Jul 2, 2024 1:47:58 PM
40.31246570404619N 107.69164723344147W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo #3 area of former discharge. A very small trickle of water was observable.

Jul 2, 2024 2:11:21 PM
40.30796701088548N 107.69017537124455W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



40.3079823916778N 107.69023446366191W

Jul 2, 2024 2:11:47 PM

Inspection Photos

Location Name: Iles

Location ID: 483727

Remediation Project #: 28246

Inspection Date: 7/2/2024

Photo #4 a frog near the gulch was observed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo #5 weir that was used in the discharge. A very small trickle was observed passing through the weir. Note: drip to the left of the weir.

Jul 2, 2024 2:12:07 PM
40.308036538772285N 107.69022750668228W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#6 Seeping spring
Gulch.

Jul 2, 2024 2:12:16 PM
40.308046555146575N 107.69023362547159W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#7 Seeping spring
Gulch.

Jul 2, 2024 2:13:20 PM
40.30830178409815N 107.68993724137545W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#7 Seeping spring
Gulch.

Jul 2, 2024 2:14:23 PM
40.30874673742801N 107.68977086059749W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#9 Seeping spring
Gulch.

Jul 2, 2024 2:14:53 PM
40.30894082039595N 107.68963322974741W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#10 Seeping spring
Gulch.

Jul 2, 2024 2:16:07 PM
40.309583712369204N 107.68979885615408W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#11 Seeping spring
Gulch.

Jul 2, 2024 2:16:37 PM
40.3097903681919N 107.6898120995611W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#12 Seeping spring
Gulch.

Jul 2, 2024 2:17:15 PM
40.309993042610586N 107.68980463966727W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#13 Seeping spring
Gulch.

Jul 2, 2024 2:17:53 PM
40.31007061712444N 107.69014787860215W





Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#14 Seeping spring
Gulch.

Jul 2, 2024 2:18:07 PM
40.31005179975182N 107.69025919027627W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 483727
Remediation Project #: 28246
Inspection Date: 7/2/2024

Photo#6 Seeping spring
Gulch.

Jul 2, 2024 2:18:42 PM
40.310083692893386N 107.69060435704887W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources