

Inspection Photos

June 28th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 322104

Inspection Document #: 714000915

Dolores County, CO

Township: NENE 19 40N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DWD 1
Location ID: 322104



6/28/24
+37.720071,-108.758516
138° SE

Inspection Photos
Location Name: DWD 1
Location ID: 322104

6/28/24
+37.719885,-108.758220
45° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of project area cut slopes that have been reduced to a slope of 3:1 and are revegetated with desirable vegetation to the 80% vegetation standard.

API #: 033-06078

Inspection Photos
Location Name: DWD 1
Location ID: 322104




Photo 3. Patches of Musk thistle and Cheatgrass observed in the northern and western portions of the disturbance.

Inspection Photos
Location Name: DWD 1
Location ID: 322104



6/28/24
+37.719555,-108.758342
250° W

Photo 4. Reference area comprised of Sage brush, Yucca and Serviceberry.