

Final Reclamation and Stormwater Inspection

Date:

06/26/2024

Operator: PDC ENERGY INC - 69175

Location ID: 472063

Inspection Document #: 708201372

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 1. Road Base material and culvert observed at the former entrance.

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 2. Culvert requires removal.

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 3. Facing north from the southern portion of the location. Reclaimed portions are not progressing towards reclamation rules and standards with non-uniform vegetation cover consisting mostly of undesirable vegetation observed.

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 4. Facing south from the northern end of the location; see comments in Photo 3.

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 5. Facing west from the eastern portion of the location; see comments in Photo 3.

Inspection Photos
Location Name: J&L Farms 31, 41-19
Location ID: 472063



Photo 6. Facing southwest from the eastern portion of the location; see comments in Photo 3.