

# Final Reclamation and Stormwater Inspection

Date: 06/26/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 306342

Inspection Document #: 708201374

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Larson USX AA 19-3

Location ID: 306342



**Photo 1.** The well location (Location ID 306342 with API 123-24480) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas. This location will remain "In-Process" until an off-location flowline abandonment notice is submitted and the active remediation project is closed and approved under a Form 27.

Inspection Photos  
Location Name: Larson USX AA 19-3  
Location ID: 306342



**Photo 2.** Facing north; see comments in Photo 1.

Inspection Photos  
Location Name: Larson USX AA 19-3  
Location ID: 306342



**Photo 3.** Facing east; See comments in Photo 1.

Inspection Photos  
Location Name: Larson USX AA 19-3  
Location ID: 306342



**Photo 4.** Facing south; see comments in Photo 1.