

Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



Staining



Staining



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



Debris



Debris. Container label? Containment?



**Beeman Oil & Gas Inc**  
**Stoddard 33-30**  
**Location ID: 423933**



**Staining around containment**




**Debris**



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



No visible display of gas calibration



Gas meter calibration overdue



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933




Debris



Debris



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



**Staining**



**Open ended load line**



**Beeman Oil & Gas Inc**  
**Stoddard 33-30**  
**Location ID: 423933**



**Staining and debris**




**Liner material in state of disrepair**



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



**Staining**



**Staining**



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



**Debris**



**Staining**



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



Staining



Staining



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



**Staining**



**Oily waste, debris and stained soil**



Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933



**Oily waste**



**Stained soil needs to be removed and disposed of properly**



**Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933**



**Location from Southwest corner**



**Location from Northwest corner**



**Beeman Oil & Gas Inc  
Stoddard 33-30  
Location ID: 423933**



**Location from Northeast corner**



**Location from Southeast corner**