

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 2139 From entrance to location



Photo # 2140 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 2141 Location



Photo # 2142 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 2143 Location



Photo # 2144 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



May 13, 2024 at 2:15:52 PM
CO

**Photo # 6804 From inspection 708903802 conducted on
05/13/2024 Unused equipment**



Jul 2, 2024 at 11:41:37 AM
CO

Photo # 2145 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPRUCE CREEK PRODUCTION PIT 14-4-794

Location #: 427810



Photo # 2146 Tank battery lacks signage