

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad

Location # 334872



Photo # 2421 From entrance to location




Photo # 2422 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad

Location # 334872



Photo # 2423 Location



Photo # 2424 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad

Location # 334872



Photo # 2425 Chemical tank is in use/used for water sampling/monitoring due to previous spill - please refer to FORM 4 SUNDRY document # 403739635

Photo # 2426 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad

Location # 334872



Photo # 2427 Solar powered SVE trailer - Please refer to FORM 27 document # 402924072 & FORM 4 SUNDRY document # 403739635

Photo # 2428 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad

Location # 334872



Photo # 2429 Location



Photo # 2430 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH/SAMPLE (J17E) Pad
Location # 334872



Photo # 2431 Debris



Photo # 2432 Some info on wellhead sign faded & becoming illegible & emergency contact # peeling