

# Inspection Photos

API: 071-07766

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast at beginning of the pre-existing access road.



## Inspection Photos



**Photo 2.** Facing northeast, repairs have been made to areas of the road and BMP's are maintained.



## Inspection Photos



**Photo 3.** Facing northwest going downhill along the road. BMP's are maintained along the road.



## Inspection Photos



**Photo 4.** Facing northwest, water bars have been put in to direct stormwater to the culvert.



## Inspection Photos



**Photo 5.** Facing northeast along the pre-existing road in the canyon bottom.



## Inspection Photos



**Photo 6.** The culverts along the road are maintained and vegetation is well established.



## Inspection Photos



**Photo 7.** Facing southeast toward the reclaimed location. Perennial vegetation has fully re-established and the location is stabilized.



## Inspection Photos



**Photo 8.** Facing southwest toward the reclaimed location. Perennial vegetation has fully re-established and the location is stabilized.



## Inspection Photos



**Photo 9.** Facing west at the location.

