

Inspection Photos

API: 071-09178

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 7/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at beginning of the reclaimed access road..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. The perennial vegetation is establishing well along the reclaimed road.



Inspection Photos



Photo 3. Facing west toward the reclaimed location. The diversion ditch has been cleaned out.



Inspection Photos



Photo 4. Facing northwest toward the upper portion of the reclamation area. The perennial vegetation is establishing well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing southwest down the slope of the reclaimed location..



Inspection Photos



Photo 6. Southwest corner facing north. The area at left side of the photo will need additional seeding to establish vegetation..



Inspection Photos



Photo 7. Facing northeast at the bottom of the location.



Inspection Photos



Photo 8. There is areas along the bottom portion that will need additional reseeding..



Inspection Photos



Photo 9. Facing northwest at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources